



JON M. HUNTSMAN, JR.
Governor


GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
February 13, 2007

Supervisor 

Mine Name: Lynn Springs Quarry
Operator Name: Bonneville Quarries, Inc.

Permit number: M0030025
Inspection Date: August 8, 2006
Time: 3:30 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:


1. This site is considered active, even though there was no activity during this inspection. There were signs of recent activity, including an excavator in the pit and gravel had been added to the access road to fill in potholes and rutted areas. Gravel was quite coarse.

There has been no expansion of the disturbed area since my last inspection. There was no trash observed other than what appeared to be an abandoned truck.

Conclusions and Recommendations:

The Forest Service was notified of site conditions (road maintenance activities and abandoned truck - they may look at this in the near future.

Continue to monitor this site when in the area.

Inspector's Signature 

LK:pb

O:\M003-BoxElder\M0030025-Lynnsprings\inspections\Insp-08082006.doc